



Products: CP10 G2

Firmware Version: 0.0.2800.80

Published Date: July 11, 2025

Copyright © 2025

Copyright Notice

This publication, including all photographs, illustrations and software, is protected under international copyright laws, with all rights reserved. Neither this manual, nor any of the material contained herein, may be reproduced without written consent of the author.

Disclaimer

The information in this document is subject to change without notice. The manufacturer makes no representations or warranties with respect to the contents hereof and specifically disclaim any implied warranties of merchantability or fitness for any particular purpose. The manufacturer reserves the right to revise this publication and to make changes from time to time in the content hereof without obligation of the manufacturer to notify any person of such revision or changes.

Limitations of Liability

UNDER NO CIRCUMSTANCES SHALL AVER BE LIABLE FOR DAMAGES OF ANY CHARACTER (E.G. DAMAGES FOR LOSS OF PROFIT, SOFTWARE RESTORATION, WORK STOPPAGE, LOSS OF SAVED DATA OR ANY OTHER COMMERCIAL DAMAGES OR LOSSES) RESULTING FROM THE APPLICATION OR IMPROPER USE OF THE AVER PRODUCT OR FAILURE OF THE PRODUCT, EVEN IF AVER IS INFORMED OF THE POSSIBILITY OF SUCH DAMAGES. FURTHERMORE, AVER WILL NOT BE LIABLE FOR THIRD-PARTY CLAIMS AGAINST CUSTOMER FOR LOSSES OR DAMAGES. AVER WILL IN NO EVENT BE LIABLE FOR ANY DAMAGES IN EXCESS OF THE AMOUNT AVER RECEIVED FROM THE END-USER FOR THE PRODUCT.

Content

Revision History and System Requirement	2
Important Notice	3
New Features	4
Problems Fixed	5
Known Issues	5



Revision History and System Requirement

Firmware Version	Region	Date	Model
0.0.2800.80	WW	July 11, 2025	CP10 G2
0.0.2800.70	WW	April 01, 2025	CP10 G2



Important Notice

1. During system upgrades, please DON'T turn off the power for any reason.
2. If the FW upgrade is not successful, please re-plug power adapter and USB cable to do FW upgrade again.



New Features

Firmware Version	New Features
0.0.2800.80	● Added MT Control Panel support for MT300 and MT100 ● Added RM support for VB370A BYOM mode. Requires VB370A firmware v0.1.1002.82 or later
0.0.2800.70	● Added BYOM controller support for an upcoming new product to be launched in Q2 2025. ● Improved UI and UX for easier navigation in Setting Page. ● Improved UI and UX for smoother navigation in Room Management. ● Added more settings to supported products in Room Management. ● Added microphone on/off and volume control features in Room Management for supported products. These features are available only when the device firmware meets the minimum required versions below: • FONE540 – v0.0.7008.02 • FONE700 – v0.0.8304.02 • VB130 – v0.0.7304.02 • VB342 Pro – v0.0.7806.02 • VB350 – v0.0.8210.02 • VC520 Pro3 – v0.0.9804.02



Problems Fixed

Firmware Version	Problem Fixed
0.0.2800.80	● Fixed CP10G2 not wake up connected cameras in Standby mode
0.0.2800.70	● Fixed some UI and UX issues.

Known Issues

Firmware Version	Description
0.0.2800.80	● Not support PAV TR211/315(N)/TR335(N) Framing features ● The RM application for VB370A BYOD mode lacked Transition and Audio Fence features.
0.0.2800.70	● On FONE540 devices running firmware versions earlier than v0.0.7008.02, the microphone on/off and volume control options will still appear in the Room Management interface; however, these controls will not function properly. To enable full functionality, users must upgrade the FONE540 firmware to version v0.0.7008.02 or later.

