



Products: VB342 Pro Firmware Version: 0.0.7802.16 Published Date: June 30, 2023

Copyright © 2023

Copyright Notice

This publication, including all photographs, illustrations and software, is protected under international copyright laws, with all rights reserved. Neither this manual, nor any of the material contained herein, may be reproduced without written consent of the author.

Disclaimer

The information in this document is subject to change without notice. The manufacturer makes no representations or warranties with respect to the contents hereof and specifically disclaim any implied warranties of merchantability or fitness for any particular purpose. The manufacturer reserves the right to revise this publication and to make changes from time to time in the content hereof without obligation of the manufacturer to notify any person of such revision or changes.

Limitations of Liability

UNDER NO CIRCUMSTANCES SHALL AVER BE LIABLE FOR DAMAGES OF ANY CHARACTER (E.G. DAMAGES FOR LOSS OF PROFIT, SOFTWARE RESTORATION, WORK STOPPAGE, LOSS OF SAVED DATA OR ANY OTHER COMMERCIAL DAMAGES OR LOSSES) RESULTING FROM THE APPLICATION OR IMPROPER USE OF THE AVER PRODUCT OR FAILURE OF THE PRODUCT, EVEN IF AVER IS INFORMED OF THE POSSIBILITY OF SUCH DAMAGES. FURTHERMORE, AVER WILL NOT BE LIABLE FOR THIRD-PARTY CLAIMS AGAINST CUSTOMER FOR LOSSES OR DAMAGES. AVER WILL IN NO EVENT BE LIABLE FOR ANY DAMAGES IN EXCESS OF THE AMOUNT AVER RECEIVED FROM THE END-USER FOR THE PRODUCT. **Content**

Revision History and System Requirement	
mportant Notice	3
New Features	4
Problems Fixed	5
Known Issues	5





Revision History and System Requirement

Firmware Version	Region	Date
0.0.7802.16	WW	June 30, 2023
0.07800.62	WW	September 6 <i>,</i> 2022
0.0.7800.56	WW	June 20, 2022
0.0.7800.52	WW	April 21, 2022
0.0.7800.48	WW	April 12, 2022



2



Important Notice

AVer Information Inc.

1. During system upgrade, please DON'T turn off the power for any reasons.

2. PTZApp2 must be upgraded to v. 2.0.1038.39 (MAC); v. 2.0.1055.56 (Windows) to support latest functions.





New Features

Firmware Version	New Features
0.0.7802.16	 When switching from any AI mode to "Manual Frame", it automatically
	triggers framing one time.
0.0.7800.62	 Support Flicker Decrease on IFP / Monitor function via running PTZApp2 in
	PC or Web page connection
	 Improve True WDR function performance
0.0.7800.56	 Improve Smart Gallery performance
0.0.7800.52	 Support AI functions via VISCA Over IP, such as audio tracking
	 Improve sensitive range while using remote control
	 Improve Auto frame performance
0.0.7800.48	 Support Smart Gallery function via running PTZApp2 in PC
	 Enlarge default audio volume
	 Improve audio tracking performance





Problems Fixed

Firmware Version	Problem Fixed
0.0.7802.16	1. Fix WDR stability
	2. Fix USB to Display description
	3. Enhance the stability of Tilt up/down value
0.0.7800.56	Fixed VISCA command: Power_Reset, Power_On, Power_Off
0.0.7800.52	N/A
0.0.7800.48	N/A

Known Issues

Firmware Version	Problem Fixed
0.0.7800.48	After device powers on, it takes around 1 min to enable Web page connection
	and audio tracking function.

