

A+ Suite Software Release Note –June 24th, 2025

VERSION	v2.7.2192.195
HARDWARE COMPATIBILITY	The following product models are supported by A+ Suite. <u>Win V2.7.2192.195</u> U50+, U70i, F17+, F50+, M15W, M70W, M15-13M, U70+, VP-1FK, F50-8M, F17-
	8M, M17-13M, VP-1HD, M70HD, F70W, F50HD, U50, U70 Mac V2.5.2161.162
	U70+, VP-1FK, F50-8M, F17-8M, M17-13M, VP-1HDN, M70HD, F70W, F50HD, U50, U70
OPERATING DEVICES / SYSTEMS	Windows 7 (32/64-bit), Windows 8 (32/64-bit), Windows 10 (32/64-bit):
	 Microsoft PowerPoint 2007 or 2010 (32-bit) (only for PowerPoint Plug- in)
	 Intel Core 2 Duo 3GHz or later x86 processor, 4GB of RAM or higher At least 900 MB of disk space
	Microsoft DirectX 9.0c installed
	Mac Users (Mac OS X 10.14):
	Minimum: Intel Core Duo 2 GHz or later x86 processors, 2 GB of RAM, 110MB free hard disk for basic installation

	[Fix] Can't support AVer Cam340 in Sphere2 side by side mode.
	[Fix] Can't upload files to YouTube.
	[Known Issue] Only generate MP4 format in high quality screen recording.
	[Known Issue] Can't open AVer Sphere2 and AVer CaptureShare at the same time.
[Win] 2.7.2170.171	WHAT'S NEW & KNOWN ISSUES
[MAC] 2.5.2161.162 Release date: February 18, 2020	[What's New] Support P2P mode with F70W new firmware version.
2020	[Fix] For U50 camera model, we fixed some integrated problems in this version . So if you cannot get U50 streaming successfully, please update to this version.
	[Fix] For Win10 PC, we fixed some integrated problems in this version. So if you cannot get camera streaming successfully, please update to this version.
	[Fix] Some anti virus softwares will pop out the alert message when installing our old software version.
	[Known Issue] P2P connection can't support Mac OS10.15.
	[Known Issue] Randomly auto disconnect within 30mins to 1 hour with F70W via P2P connection.
	[Known Issue] Sometimes you may get the fail if you change resolution in P2P mode. (Network issue) Please restart the app for now. Issue to be resolved in future releases.
	[Known Issue] Users cannot change M15W & M70W flicker in software. Issue to be resolved in future releases. [SPH2W-65]
	[Known Issue] Users cannot use high quality capture with M15W & M70W in software. Issue to be resolved in future releases. [SPH2W-63]
	[Known Issue] Window10 has updated the video player recently. Users cannot use windows default video player to play the files in software. Issue to be resolved in future releases. [SPH2W-68]
[Win] 2.7.2160.161	WHAT'S NEW & KNOWN ISSUES
Release date: September 18 2019	[What's New] Support new DocCam models: M15W, M70W, M15-13M.
	[Fix] If you can't get the U50 streaming from the software, please update it with the current version.
	[Limitation] Need do the M15W, M70W's Wi-FI settings from the Options -> Camera Settings -> Advanced settings in Sphere2
	[Known Issue] Users cannot change M15-13M flicker in software. Issue to be

	resolved in future releases. [SPH2W-52]
	[Known Issue] The resolution change needs to take about 10 sec. in Sphere2 with M15W/M70W's Wi-Fi mode. Issue to be resolved in future releases. [SPH2W-53]
	[Known Issue] No support EAP-TLS network access control setup from the software's Wi-Fi information settings. (Options -> Camera Settings -> Advanced settings in Sphere2) Issue to be resolved in future releases. [SPH2W-54]
	[Known Issue] Dropbox stopped working because Dropbox changed their API. Issue to be resolved in future releases.
[Mac] 2.5.2154.155 Release date: September 18 2019	[Fix] If you can't get the U50 streaming from the software, please update it with the current version.
	[Known Issue]Need to submit the Mac OS permission when the first time to use in Mac OS10.14.5. It is a new security and policy in the OS. [SPH2M-4]
	[Known Issue] Dropbox stopped working because Dropbox changed their API. Issue to be resolved in future releases. [SPH2M-1]
	[Known Issue] Sometimes the app will be unstable when close it in OS 10.14.5 & 10.13.6. Issue to be resolved in future releases.[SPH2M-2]
[Win] 2.5.2152.153 [MAC] 2.5.2152.153	WHAT'S NEW & KNOWN ISSUES
Release date: March 6 2019	[What's New] Support U70+ / U50 with new hardware.
	[Fixes] The progress will be frozen in 99% when users upload video to YouTube.
	[Limitation] Office plug-in for excel need to load manually.
	[Limitation] If users have installed office plug-in in Office 2011, please uninstall the older version first because we only support Office 2016 64bit in new version.
[Win] 2.5.2143.144	WHAT'S NEW & KNOWN ISSUES
[MAC] 2.5.2143.144 Release date: Aug 2 2018	[What's New] Support U70+
	[What's New] Support Mac 64bit (Office plug-in support Office 2016 64bit above)
	[Fixes] SSO account log-in issue
	[Fixes] Dropbox stopped working because Dropbox changed their API. Issue to be resolved in future releases.
	[Limitation] Office plug-in for excel need to load manually.
	[Limitation] If users have installed office plug-in in Office 2011, please uninstall
	the older version first because we only support Office 2016 64bit in new version.
[Win] 2.5.2136.137 Release date: Nov 29 2017	WHAT'S NEW & KNOWN ISSUES
	[What's New] Supports Windows 4K display output.

	[Limitation] In 4K output, only the text can auto adjust by font size and resolution.
	[Limitation] Flash, Twain, Office Plug-in can't auto adjust by font size nor resolution.
	[Known Issue] Dropbox stopped working because Dropbox changed their API. Issue to be resolved in future releases.
[Win] 2.5.2132.133	WHAT'S NEW & KNOWN ISSUES
[MAC] 2.5.2132.133 Release date: Aug 24 2017	[Fixes] If you are having U50 cameras showing disconnection or connection issues with the message "USB does not have enough bandwidth", please update your software with the current version.
	[Limitation] In order to fix the stability of the software, you can no longer display the AVer USB camera stream on multiple apps (for example, you cannot have both Sphere2 and Widget mode running at the same time, etc). Please close one application for the other application to be able to grab the USB stream.
	[Limitation] If you are using Flash or PPT, you need to select the camera source via the "Device Manager Tool".
[Win] 2.5.2118.119	WHAT'S NEW & KNOWN ISSUES
[MAC] 2.5.2118.119 Release date: Jan 6 2017	Support F50-8M WIFI /F17-8M
[Win] 2.5.2114.115	WHAT'S NEW & KNOWN ISSUES
[MAC] 2.5.2114.115 Release date: Dec 29 th 2016	Support F50-8M
[WIN] 2.5.2110.112	WHAT'S NEW & KNOWN ISSUES
[MAC] 2.5.2106.107 Release date: Oct 27 th 2016	[Known Issue] On newer MacBook Air with USB Type C ports, Sphere2 might not be able to access cameras (showing "Blocked" on the screen). We are still working on a permanent fix to this (MAC only)
	[Known Issue and Fix] If your computer has recently been updated to the Windows Anniversary edition, your webcams and certain AVer cameras might
	not work anymore. Please search for Microsoft patch KB3193494 and KB3194496 in order to fix this issue or simply make sure your Windows is updated to the latest patch via Windows update.
	New language "Italian" supported (WIN/MAC)
	Fixed YouTube and Google Drive upload issue (WIN only)
	Partial fix for Windows multiple user access to Sphere2. If user A simply closes "Sphere2" without having to log off, user B should still be able to access Sphere2 on the same computer. (Win only)
	Removed Floating toolbox teaching game (WIN/MAC)




	Image: Sector
[WIN] 2.5.2097.98	WHAT'S NEW & KNOWN ISSUES
[MAC] 2.5.2097.98 Release date: July 22nd 2016	Added Spanish language support
	Fixed MAC version Flash plugin
[Win] 2.5.2095.96	WHAT'S NEW & KNOWN ISSUES
[MAC] 2.5.2095.96 Release date: June 6 th 2016	Added support for the U70
	Fixed F70W WiFi connection issue
	Fixed support for the AVer Flash Plug-in for Windows 7/8/10
[Win] 2.5.2077.78 [MAC] 2.5.2082.84	WHAT'S NEW & KNOWN ISSUES
Release date: Feb 22 nd 2016	Updated to support Windows 10. If you encountered a warning message from Windows 10 during installation about the authentication of the publisher, allow the installation process to go through.
	Widget mode screen is now movable across the screen.
	Fixed compatibility issue with the AVerMedia H788 TV Tuner card.
	Fixed MAC driver and support UVC/non-UVC h.264 format.
	Fixed Firmware upgrade (F70W) issues in Software advanced settings.
	Fixed compatibility for Mac OS 10.10 with Adobe Flash
	Facebook upload feature has been removed.
	Full screen recording is only available for Mac OS 10.9 or higher. If you are experiencing sluggishness in your computer, please upgrade to MAC OS 10.9

Office Plugins will not be installed by default unless user selects the option to install the Plugins during the setup process.
Added ability to capture document camera visual only under Widget Mode.
Added search TabCam by IP address feature For networks who block broadcast traffic such as UPNP (needed for Sphere2 to auto discover available TabCam on the network), now it is possible to search and add any TabCam into the software by just using the IP address of the TabCam.
Fixed Sphere2 requiring local admin rights to work This version removes the restriction. Admin rights is only needed during the installation process.
OCR Engine The OCR support has been discontinued.
MS Excel / MS Word Plug-in The MS Excel and Word Plug-in installation option is only available on our CD version of the software as it requires access to the OCR engine.
MS Plug-in does not work with MS Office 64bit versions Please note that the Plug-in for PowerPoint, Word and Excel does not work in the 64bit versions of MS Office.
MS Office Plug-in Mac version MS Office Plug-in for the Mac version currently only supports Office 2011.

MORE HELP	Toll free 1.877.528.7824
	Email: <u>support.ppdusa@aver.com</u>
	http://www.averusa.com