



Product A+ Interactive Software

VERSION Win V1.7.1.13, Mac V1.7.1.6

HARDWARE COMPATIBILITY The following product models are supported by the A+1.7 .
V300AF ASIC, SPC300 ASIC, SPC300 +, CP130, CP150, CP300, SPB350, SPB370, CP135, CP155, CP355, V355AF, V310AF, SPB350+, V300AF+, F30, F50, U10, U15, AP20, M50, W30

OPERATING SYSTEMS Windows XP Users (SP3):

Minimum: Intel Pentium III 1 GHz or later x86 processors, 1GB of RAM, 100MB free hard disk for basic installation

Recommended: Intel Core 2 Duo 1.66GHz or later x86 processor, 1GB of RAM or higher.

Windows Vista (32 & 64 bit):

Minimum: Intel Core Duo 1.5 GHz or later x86 processors, 1 GB of RAM, 100MB free hard disk for basic installation (without content in Gallery)

Recommended: Intel Core 2 Duo 1.66GHz or later x86 processor, 2GB of RAM or higher.

Windows 7 (32 & 64 bit):

Minimum: Intel Pentium III 1 GHz or later x86 processors, 1 GB of RAM, 100MB free hard disk for basic installation (without content in Gallery)

Recommended: Intel Core 2 Duo 1.66GHz or later x86 processor, 2GB of RAM or higher.

Mac Users (Mac OS X 10.5.8/10.6.x/10.7.1):

Minimum: Intel Core Duo 1.83 GHz or later x86 processors, 1 GB of RAM, 100MB free hard disk for basic installation (without content in Gallery)

Recommend: Intel Core 2 Duo 2.0 GHz or later x86 processor, 2GB of RAM or higher.



Product A+ Interactive Software

WHAT'S NEW

[Win] 1.7.1.13

Add official support for AVerVision U15

[Win] 1.7.1.11 / [MAC] 1.7.1.6

Add official support for W30

[Win] 1.7.1.5 / [MAC] 1.7.1.4

Change aspect ratio to 4:3 when bringing in video stream from the AVerVision U10.

[Win] 1.7.1.4 / [MAC] 1.7.1.3

When the AVerVision Document Camera icon is launched, the system will not modify the current mode on the Document Camera.

KNOWN ISSUES

[MAC]

AP20T and AP20S signals display abnormally in Device Management.

In certain instances, if the AP20T and AP20S devices are on when you open the Device Management; you could get the display of the devices showing an abnormal status. But the student pen can still work.

The window can't be moved when AVerVision is recording.

[Win]

The live stream of AVerVision might pause when doing some undo procedures.

It's a random issue and it happens when CPU usage too high.

When using the recording function in A+, the mouse cursor might flicker.

It's a random issue and it happens when CPU usage too high.

After AVerVision recording, the snapshot preview of video is black.

The video can still be played back normally.

The recorded video might not play well in certain conditions. (Vista OS)

It's a random issue and it happens when CPU usage too high.



Product	A+ Interactive Software
RELEASE DATE	March 5, 2012

HELP

Toll free 1.877.528.7824

Email: support.ppdusa@aver.com

<http://www.averusa.com>