

[Win] AVerTouch Software Release Note – Sep 12th, 2023

VERSION	v1.3.2084.0
HARDWARE COMPATIBILITY	The following product models are supported by AVerTouch.
	U50+ v2.0000.04, U70i v1.0.0002.09, A30 v5.10.0010.11, F17+ v5.8.0000.05, F50+
	v5.9.0000.04, M70W(v2) v5.7.0000.04, M5 v0.0.0015.16, M15W v5.0.0032.33, M70W
	v5.1.0038.42, M15-13M v5.2.0014.15, M11-8M v6.0.0021.22, M90UHD v5.4.0007.08
	U50, U70+, F17-8M, F50-8M, M17-13M
OPERATING DEVICES / SYSTEMS	Win OS 7, Win OS 10, Win OS 11
Related Software	Wi-Fi Dongle driver_5.0.9 / Uninstall dongle driver

	WHAT'S NEW & Improvement
v1.3.2084.0 Release date: Sep 12th, 2023	[New] New DocCam model supported: AVerVision U50+
	[New] New wireless connection mechanism via PC hotspot: New mechanism of Windows PC wireless connection.
	[New] Add plug-and-play USB camera in system settings: users can freely choose to turn on/off the plug-and-play USB camera function. The default is on.
	[Improvement] Improve user experience of FW Update Tool on Windows PC
	[Improvement] Remove Quick Help Guide from AVerTouch StartUp Setup.
	[Improvement] Add tooltip for Microphone Selection function
	BUG FIXED
	[Improvement] Remove the reboot Wizard after installing the AVerTouch software: No need to reboot the computer after installing the AVerTouch software on Windows PC.
	<u>Issues</u>
	None

Known issues	•	UI display issues in 4K resolution. Annotation cannot follow the camera image rotate.
Limitation	•	Cannot set WPA-PSK network in wireless camera. Now we only support WPA2-PSK for wifi setting in AVerTouch. We are working on the additional

format includes the WPA-PSK.

- Doesn't support extend display screen now, it can't be recorded and captured.
- Sometimes camera cannot be connected that it also is based on your network status. Please check your network and reconnect it again.
- Privacy policy and terms of service page pop out the empty webpage if you don't connect to the Internet.