



Products: PTZApp for Mac OS

Software Version: 1.3.1060.63

Published Date: January 29, 2019

Copyright © 2016

Copyright Notice

This publication, including all photographs, illustrations and software, is protected under international copyright laws, with all rights reserved. Neither this manual, nor any of the material contained herein, may be reproduced without written consent of the author.

Disclaimer

The information in this document is subject to change without notice. The manufacturer makes no representations or warranties with respect to the contents hereof and specifically disclaim any implied warranties of merchantability or fitness for any particular purpose. The manufacturer reserves the right to revise this publication and to make changes from time to time in the content hereof without obligation of the manufacturer to notify any person of such revision or changes.

Limitations of Liability

UNDER NO CIRCUMSTANCES SHALL AVER BE LIABLE FOR DAMAGES OF ANY CHARACTER (E.G. DAMAGES FOR LOSS OF PROFIT, SOFTWARE RESTORATION, WORK STOPPAGE, LOSS OF SAVED DATA OR ANY OTHER COMMERCIAL DAMAGES OR LOSSES) RESULTING FROM THE APPLICATION OR IMPROPER USE OF THE AVER PRODUCT OR FAILURE OF THE PRODUCT, EVEN IF AVER IS INFORMED OF THE POSSIBILITY OF SUCH DAMAGES. FURTHERMORE, AVER WILL NOT BE LIABLE FOR THIRD-PARTY CLAIMS AGAINST CUSTOMER FOR LOSSES OR DAMAGES. AVER WILL IN NO EVENT BE LIABLE FOR ANY DAMAGES IN EXCESS OF THE AMOUNT AVER RECEIVED FROM THE END-USER FOR THE PRODUCT.

Content

Revision History and System Requirement	. 2
Important Notice	. 3
New Features	. 4
Problems Fixed	. 6
Known Issues	. 7





Revision History and System Requirement

Software Version	Region	os	Date	Model
1.3.1060.63	WW	MAC	January 28. 2019	All USB Camera
1.3.1059.60	WW	MAC	November 26, 2018	All USB Camera
1.3.1052.59	WW	MAC	October 12,2018	VB342/CAM540/VC 322/
				VC520+/CAM520/
				CAM530/CAM340
1.3.1050.52	WW	MAC	March 16, 2018	VC 322/
				VC520+/CAM520/CAM5
				30/CAM340
1 2 1045 40	ww	MAC	December 27, 2017	VC 322/VC520/CAM520/
1.3.1045.48				CAM530/CAM340
1.2.1024.45	WW	MAC	August 7, 2017	VC520/CAM520/
				CAM530/CAM340
1.2.1025.30	WW	MAC	August 5,2016	VC520/CAM520/CAM530
1.2.1021.25	WW	MAC	May 25,2016	VC520/CAM520/CAM530
1.0.1019.21	WW	MAC	January 11,2015	VC520/CAM520/CAM530
1.0.1011.19	WW	MAC	December 14, 2015	VC520/CAM520
1.0.100.11	WW	MAC	September 2,2015	VC520






Important Notice

- 1. PTZ app is a software tool used to configure and upgrade AVer USBCam series
- 2. Supports Mac OS 10.9/10.10/10.11.





New Features







1.3.1052.59	Support CAM540 flip image setting			
	Support VB342 install driver			
1.3.1050.52	None, this version is for bug fixed.			
1.3.1045.48	Support VC322			
1.2.1024.45	None, this version is for bug fixed.			
1.2.1025.30	Support AEC/NR enable/disable selection.			
	2. Add Home position selection.			
	3. Add Suspend position selection.			
	*Firmware must be upgraded to v0.0.0016.06 for VC520/CAM520 & v.0.0.1002.04			
	for CAM530.			
1.2.1021.25	1. Adds remote control selection – User may select the type of remote control			
	used.			
	2. Supports Hotkey function.			
	3. Supports camera select function on remote control.			
	4. Adds "auto" function selection for backlight compensation.			
	5. Adds continuous auto focus function selection.			
1.0.1019.21	Supports CAM530			
1.0.1011.19	None new features			
1.0.100.11	The 1st release			





Problems Fixed

Software Version	Problem Fixed				
1.3.1060.63	None				
1.3.1059.60	None				
1.3.1052.59	None				
	Bug fixed.				
	1. For Macmini 10.10, when user open PTZApp and connect USB camera, and then				
	execute ISP under view seeing environment. It still jump a windows to block ISP.				
1.3.1050.52	2. Use VC322 to connect Mac and ZOOM ROOM at the same time. When users				
	execute ISP twice, it will jump "Upload file fail" information at the second times.				
	Users open PTZApp and Ucam at the same time. When user click auto update at				
	PTZApp. It will jump a message "the version doesn't match the devices."				
1.3.1045.48	None				
	"Upload file failed!" pops-up when performing ISP PTZApp at MAC				
4.0.4004.45	10.11.				
1.2.1024.45	The device is incompatible with this version! Pops-up when performing				
	ISP PTZApp at VC520 at MAC10.11.				
1.2.1025.30	None				
4.0.4004.05	"Upload file failed!" pops-up when performing ISP PTZApp under				
1.2.1021.25	MAC10.9.				
1.0.1019.21	None				
	Let PTZ app could record the last setting information on BLC(Back				
4.0.4044.40	Light Compensation).				
1.0.1011.19	2. Support Multi-Device. (VC520/CAM520)				
	3. Support new model.(CAM520)				
1.0.100.11	None				





Known Issues

Software Version	Known Issues
1.3.1060.63	None
1.3.1059.60	None
1.3.1052.59	None
1.3.1050.52	None
1.3.1045.48	None
1.2.1024.45	None
1.2.1025.30	None
1.2.1021.25	None
1.0.1019.21	None
1.0.1011.19	None
1.0.100.11	None
1.3.1052.59	"Upload file failed!" pops-up when performing ISP
	PTZApp under MAC10.9.
1 2 1050 52	"Upload file failed!" pops-up when performing ISP
1.3.1050.52	PTZApp under MAC10.9.
1.3.1045.48	None

