

## [Win] AVerTouch Software Release Note – Feb 16, 2023

VERSION	V1.3.2073.0
HARDWARE	The following product models are supported by AVerTouch.
COMPATIBILITY	
	U70i v1.0.0002.09, A30 v5.10.0010.11, F17+ v5.8.0000.05, F50+ v5.9.0000.04, M70W(v2)
	v5.7.0000.04, M5 v0.0.0015.16, M15W v5.0.0032.33, M70W v5.1.0038.42, M15-13M
	v5.2.0014.15, M11-8M v6.0.0021.22, M90UHD v5.4.0007.08
	U50, U70+, F17-8M, F50-8M, M17-13M
OPERATING	Win OS 7, Win OS 10, Win OS 11
DEVICES /	
SYSTEMS	
Related Software	Wi-Fi Dongle driver_5.0.9 / Uninstall dongle driver

V1.3.2073.0 Release date: Feb 16, 2023	- [New] New DocCam model supported: AVerVision U70i - [New] New WiFi connection mechanism: New mechanism of M15W, M70W and M70W(v2) connection. Simply the connection flow of WiFi and transfer to USB connection when failed.
	BUG FIXED  Fixed — When a user cancels login Google Classroom, it will cause AVerTouch to crash.  Fixed — Display timer can't setting issue.
	<u>Issues</u> None

Known issues	•	UI display issues in 4K resolution.  Annotation cannot follow the camera image rotate.
Limitation	•	Cannot set WPA-PSK network in wireless camera. Now we only support WPA2-PSK for wifi setting in AVerTouch. We are working on the additional format includes the WPA-PSK.  Doesn't support extend display screen now, it can't be recorded and captured.  Sometimes camera cannot be connected that it also is based on your network status. Please check your network and reconnect it again.  Privacy policy and terms of service page pop out the empty webpage if you

don't connect to the Internet.	