


[Mac] CaptureShare Software Release Note – Dec 11th, 2023

VERSION	1.3.2109.0
HARDWARE COMPATIBILITY	<p>The following product models are supported by CaptureShare.</p> <p>Pro AV PTZ Camera:</p> <ul style="list-style-type: none"> • PTZ310/PTZ310N/PTZ330/PTZ330N 0.0.0000.60 and above • TR310/TR311/TR311HN/TR313/TR331/TR333 0.0.0000.16 and above • TR530/TR320 0.0.1000.47 and above • TR333V2/TR323NV2/TR313V2/TR311HWV2 0.1.0000.16 and above • PTZ310UV2/PTZ310UNV2/PTZ330UV2/PTZ330UNV2/PTZ211/PTZ231 0.0.0000.12 and later • DL30 7.0.0000.08 and later <p>Medical Camera:</p> <ul style="list-style-type: none"> • MD330U/MD330UI • MD120U series <p>DocCam:</p> <ul style="list-style-type: none"> • U50/U70/U70+/F17-8M/F50-8M/M17-13M/M15-13M/M11-8M/M90UHD/M15W/M70W/M5/F50+
OPERATING DEVICES / SYSTEMS	Mac 10.15 Mac 11 Mac 12

<p>1.3.2109.0</p> <p>Release date: Dec 11th, 2023</p>	<p><u>WHAT'S NEW & Improvement</u></p> <ul style="list-style-type: none"> • Supports Ukrainian • Supports PTZ211/PTZ231 <p><u>Features Improvement</u></p> <p><u>KNOWN ISSUES</u></p>
<p>1.3.2099.0</p> <p>Release date: Aug 17th, 2023</p>	<p><u>WHAT'S NEW & Improvement</u></p> <ul style="list-style-type: none"> • Support MD120 series • Support PTZ Camera PTZ310UV2/PTZ310UNV2/PTZ330UV2/PTZ330UNV2 <p><u>Features Improvement</u></p> <ul style="list-style-type: none"> • Fix firmware update message of synchronization • Fix power frequency default value • Fix some model name cut issue • Fix AVerMedia BU113 setting empty issue • Fix USB reconnect detection issue <p><u>KNOWN ISSUES</u></p>
<p>1.3.2089.0</p> <p>Release date: Apr 25th, 2023</p>	<p><u>WHAT'S NEW & Improvement</u></p> <ul style="list-style-type: none"> • Support PTC330UNV2 <p><u>BUG FIXED</u></p> <ul style="list-style-type: none"> • Some UI and wording fixed <p><u>KNOWN ISSUES</u></p> <ul style="list-style-type: none"> • N/A
<p>1.3.2087.0</p> <p>Release date: Apr 7th, 2023</p>	<p><u>WHAT'S NEW & Improvement</u></p> <ul style="list-style-type: none"> • Support MD330U New Features • Support AVerMedia BU113

	<p><u>BUG FIXED</u></p> <ul style="list-style-type: none"> • MD330U power off will stop streaming but still can be found from IPCam Utility <p><u>KNOWN ISSUES</u></p> <ul style="list-style-type: none"> • Camera name cut on some long string models. • Firmware update failure asynchronous • Power frequency default value error. • Basic image setting is empty on AVerMedia BU113 • Abnormal UI for 480p or lower streaming format • USB disconnection retry issue • No internet connection will randomly cause app no response and show loading.
<p>1.3.2081.0 Release date: Jan 7th, 2022</p>	<p><u>WHAT'S NEW & Improvement</u></p> <ul style="list-style-type: none"> • [New] Support MD330U  <p><u>BUG FIXED</u></p> <p>None</p>
<p>1.3.2077.0 Release date: October 3, 2022</p>	<p><u>WHAT'S NEW & Improvement</u></p> <ul style="list-style-type: none"> • [New] Support Audio Delay <p>Other settings/Advance Setting</p>

Known Issues	<ul style="list-style-type: none"> • UVC streaming display isn't workable with <NDI/Streaming only mode>, but users still can select it in the list includes 3rd party Software. <ul style="list-style-type: none"> • We are working on the fix for next release. • Workaround: Please change the camera mode to “USB only”. • Camera 4K resolution only can be selected in USB only mode. <ul style="list-style-type: none"> • Workaround: Switch the mode from others to “USB only” mode in web settings.
Limitation	<ul style="list-style-type: none"> • DL/PTZ/TR camera models don't have the brightness settings in CaptureShare. <ul style="list-style-type: none"> • It can be adjusted in web settings.